

UN-ED609



การตรวจสອบสภาพอากาศสິ່ງແວດລ້ອມ

การตรวจสອບອຸດຸນີຍົມວິທີຢາສິ່ງແວດລ້ອມສາມາດຄຕຣວຈສອບອຸນຫກູມີແລະຄວາມເຊັ້ນ
ຄຸນພາພາກາສ ແລະເສີຍງຽບກວນຂອງສປາພແວດລ້ອມໃນເນື່ອງໄດ້ແບບເຮັຍລໄກນີ
ແລະສາມາດຄເຊື່ອນໄອຍືກັບໜັງຈອບນາດໃໝ່ເພື່ອສ່າງຂ້ອມູລອຸດຸນີຍົມວິທີຢາສິ່ງແວດລ້ອມ
ໄປຢັງໜັງຈອບນູລ LED ພຣອນກັນເພື່ອແສດງ

ເຄື່ອງວັດສປາພາກາສບາດເລັກ

ສານີຕຣວຈສອບອຸດຸນີຍົມວິທີຢາ RDM
ຊັບສິນໃຫຍ່ເຫັນເຊື່ອຮົດກັນສັນຍົກທີ່ສຸດໃນອຸດສາກຣມ
ຮວມກຳໜີແວດລ້ອມຮັກແລະພາຣາມີເຕອຣີອຸດຸນີຍົມວິທີຢາ
ແລະສາມາດຄໃຫ້ກັນອຍ່າງແພຣ່າລາຍໃນດ້ານອຸດຸນີຍົມວິທີຢາ
ກາປກປ້ອງສິ່ງແວດລ້ອມ ຜູນໃນເນື່ອງ ເນື່ອງອັຈອັຍະກາຮນສ່າງ ໄຟຟ້າ
ກາເກະຕຣແລະສມາຮັກ ໄຟຄົນນ ໂດຍມີຄໍາຄວາມເສັ່ກຍີໃນຮະຍະຍາວ
ຂອງອຸນຫກູມີ $\pm 1^{\circ}\text{C}$ / ປີ ແລະຄວາມເຊັ້ນສັນພັນນີ $\pm 1\%$ RH / ປີ

ຄຸນສມບັດຂອງຜລິຕັກັນກົງ

1. ໃຫ້ພລັງງານຕໍ່າມາກ (0.2W) ແນະເອຢ່າງຍິ່ງສໍາຮັບຮະບບກີ່ໃຫ້
ພລັງງານແບຕາເຕອຣີກີ່ມີຄວາມຕ້ອງການໃຫ້ພລັງງານສູງ
2. ບ່ວງອັນພຸດພລັງງານກວ້າງ 9 ~ 35V;
3. ດ້ວຍຟັງກີ່ຂັ້ນກາຈັດເກີບຂ້ອມູລກາຮວດ (ມກຣາຄມຄົ່ງຮັນວາຄມ)
ເພື່ອໃຫ້ມັ້ນໃຈຄົ່ງຄວາມສມບູຮຸນົນຂອງຂ້ອມູລກາຮວດ
4. ດ້ວຍຟັງກີ່ຂັ້ນນາພິກາປົງກົນກີ່ມີຄວາມແມ່ນຢໍາສູງ
5. ປລອກປ້ອງກັນເກຣດອຸດສາກຣມບໍ່ຍີໃຫ້ອ້າຍກາຮນໃຫ້ງານກາຄສນາມ
ຍາວນານກວ່າ 10 ປີ
6. ກາຮນປ້ອງກັນສ່ວນຕ້ອງປະສານກາງໄຟຟ້າຮະດັບອຸດສາກຣມ
7. ໂປຣໂຕຄອລເອາກົກພຸດຂ້ອມູລມາຕຣຈູານIP66



Performance parameters

គុណសមប័ត្រ

Atmospheric Temperature		Wind Speed		Sun Radiation	
Measurement Methods	NTC	Measurement Methods	Ultrasound	Measurement Methods	Silicon Photodetector
Measuring Range	-50~80°C	Measuring Range	0~60m/s	Wavelength Range	400 nm ~ 1100nm
Resolution	0.1°C	Resolution	0.1m/s	Measuring Range	0 ~ 2000w/m2
Sensor Precision Spend	± 0.1°C	Sensor Precision Spend	±0.3m/s or 3%	Sensor Precision Spend	Better than 5%
Atmospheric Temperature		Response Threshold	0.3m/s	Resolution	1w/m2
Measurement Methods	Capacitive	Unit	m/s; km/h	UV Index	
Measuring Range	~100%RH	Wind Direction		Measurement Methods	Photosensitive Element
Resolution	0.1%RH	Measurement Methods	Ultrasound	Wavelength Range	290 nm ~ 400nm
Sensor Precision Spend	0.8%RH	Measuring Range	0~360°	Measuring Range	0 ~ 15UVI
Atmospheric Pressure		Resolution	0.1°	PM2.5	
Measurement Methods	MEMS Sensor-Capacitive	Sensor Precision Spend	<3°, rms error, since 1.0 m/s	Monitoring range	0 ~ 1000ug/m3
Measuring Range	10~1100hPa	Response Threshold	0.3m/s	Measurement Methods	Laser Scatter/Fan
Resolution	0.1hPa	Rain fall		Sensitivity	0.3ug/m3
Sensor Precision Spend	±1.0hPa	Measurement Methods	Optical Scattering	Precision	15%或 +10 ug/m3
Unit	hPa	Measuring Range	Unlimited	Noise	
		sensor precision Spend	Better than 4%	Measurement Methods	Semiconductor
		Resolution	0.001mm/0.01 mm/0.2 mm	Monitoring range	30 ~ 130dB(A)
				Precision	1dB

